

CABIN HEAVY CONDENSATION

Reference: 21.00.00.068

Issue date: 01-FEB-2024

Last check date: 01-FEB-2024

Status: Closed

A/C type/serie: A321

ATA: 21-00, 25-80, 53-20, ...

Engine manufacturer:

Supplier:

Purpose / Reason for revision: Template update, TFU closure

 Engineering Support

Status: Closed

Issue Description / Consequence

- Heavy condensation has been observed in the cabin of recent A321 aircraft.
- Main cabin and structure impacted areas are located close to the PAX door 2 and 3.
- Water condensation leaks are mainly found during climbing and descent phases.
- Consequence: Cabin elements and passenger comfort can be impacted in case of heavy condensation.

**Root Cause / Investigation**

Cabin condensation contributors are:

- Long flights, around 6 hours,
- Flights between cold and warm world areas,
- Full PAX density,
- Short turn-around.
- A/C investigations launched in order to perfectible installation at insulation blankets overlapping and cut-outs were found.

Terminating ActionATA 25 & 53 SBs issues have been provided to contain "*rain in the plane*" phenomenon:

- Improvement of the installation of the insulation blankets
- Longer water seals on the sides of the OHSC and Door 2&3 frame linings
- Structure drainage solution installing a gutter above PAX door 3 & PAX door 2

Applicability:

A321

Reference / Documentation:

MOD 160338 - MP K30142 - SB 25-1BGG & SB 25-1BL3

MOD 161847 - MP K30009

MOD 164220 - MP K32217

MOD 160425 - MP K30481

MOD 160392 - MP K30339 - SB 25-1BGH & SB 25-1BL4

MOD 162174 - MP P20412 - SB 25-1BJ5 & SB 25-1BJ6

MOD 162307 - MP P20422

Description

Condensation is a normal phenomenon on all Airbus aircraft.


Indeed, humid air coming from the cabin condenses at the contact of the cold aircraft structure.

Recently, heavy condensation [and "rain in the plane"](#) have been observed in the cabin of recent A321.


Main cabin and structure impacted areas are located in the centre fuselage, close to the PAX doors 2 and 3.



Water condensation leaks in the cabin (["rain in the plane"](#)) are mainly observed during climbing and descent phases.



Flight phases where condensation is mainly experienced



Main location where condensation is mainly experienced

Consequence

Water drops are observed coming from the cabin ceiling panels which may generate passenger discomfort. At the upper side of the fuselage, after removal of the ceiling panels, insulation blankets were found wet.



Carpets close to PAX doors 2 and 3 were also found wet.



Repercussions on A/C Operations

Cabin elements and passenger comfort can be impacted in case of heavy condensation.

Investigation Status

Heavy condensation was already observed several years ago.

Investigations identified the following cabin contributors:

- Long flights, around 6 hours,
- Flights between cold and warm world areas,
- Full PAX density,
- Short turn-around.

Recent investigations have been performed to identify contributors to the abnormal water penetration in the cabin. Regarding insulation blankets, some overlapping installations and cut-outs have been found perfectible.


Permanent Solution

ATA 25 & 53: SBs have been issued to improve drainage and decrease "*rain in the plane*" phenomenon.


Results of the cabin items evaluation been satisfying, the following modifications at the doors 2 and 3 areas will be available via Airbus SBs:



Improvement of the installation of the insulation blankets,




Longer water seals on the side of the OHSC.





By the meantime, structure drainage solution introduced by SB53-1327 will be improved with a new modification installing a gutter above PAX door 3.

Similar modification were introduced at PAX door 2 with SB 25-1BJ5.



Hereafter are defined all the modifications and SBs available that contribute to reduce heavy condensation effects and improve passengers comfort:



INSULATION MOD





OHDS SEALING



DRAINAGE OPTIMIZATION

A321neo	ST2	PRODUCTION	As per manufacturing best practice	MOD 160425 MP K0481	NOT AVAILABLE
		SB	SB 25-1BGG MOD 160338 MP K30142	SB 25-1BGH MOD 160392 MP K30339	Door 2 SB 25-1BJ5 MOD 162174 MP P20412 MOD 162307 MP P20422 Door 3 SB 53-1327 MOD 162472 MP K30828 MOD 37713 MP K11582
A321LR	ST6	PRODUCTION	As per manufacturing best practice	MOD 160425 MP K30339	NOT AVAILABLE
	ST8	SB	SB 25-1BL3 MOD 160338 MP K30142	SB 25-1BL MOD 160392 MP K30339	Door 2 SB 25-1BJ6 MOD 162174 MP P20412 MOD 162307 MP P20422 Door 3 SB 53-1392 MOD 162472 MP K30828 MOD 37713 MP K11582
		PRODUCTION	MOD 161847 MP K30009 MOD 164220 MP K32217	MOD 161847 MP K30009 MOD 164220 MP K32217	MOD 160542 MP K30545
		SB	NOT AVAILABLE	NOT AVAILABLE	NOT AVAILABLE





[Survey for the Engineering Support section](#)



General Information

Potential impact:	PAX Comfort		
Key information:	In-Service Issue		
Solution benefit:			
First issue date:	21-MAR-2016	Issue date:	01-FEB-2024
Last check date:	01-FEB-2024		

Technical parameters

ATA:	21-00, 25-80, 53-20, 53-40
A/C type/serie:	A321
Engine:	
Engine manufacturer:	
Fault code/ECAM warning:	
FIN:	
Part Number:	
Supplier:	

Attachments

N/A

Links

Other articles (ISI/TFU):

- 52.10.00058

Airnav documents:

- MOD 160338, MOD 160392, MOD 160425, MOD 161796, MOD 161847, MOD 162174, MOD 162307, MOD 162472, MOD 164220, MOD 37713

- MP K11582, MP K18489, MP K30009, MP K30142, MP K30339, MP K30481, MP K30828, MP K32217, MP P20412, MP P20422
- SB 25-1BGG, SB 25-1BGH, SB 25-1BJ5, SB 25-1BJ6, SB 25-1BL3, SB 25-1BL4, SB 53-1327, SB 53-1392

© Airbus SAS, 2024. All rights reserved. Confidential and proprietary document. The technical information provided in this article is for convenience and information purposes only. It shall in no case replace the official Airbus technical or Flight Operations data which shall remain the sole basis for aircraft maintenance and operation. These recommendations and information do not constitute a contractual commitment, warranty or guarantee whatsoever. They shall not supersede the Airbus technical nor operational documentation; should any deviation appear between this article and the Airbus or airline's official manuals, the operator must ensure to cover it with the appropriate document such as TA, FCD, RDAS.

Access to WISE is supplied by Airbus under the express condition that Airbus hereby disclaims any and all liability for the use made by the user of the information contained in WISE. It shall be used for the user's own purposes only and shall not be reproduced or disclosed to any third party without the prior consent of Airbus.