



CFM56-5B

## SERVICE BULLETIN

ENGINE - Fan and Booster Assembly (72-21-00) - Fan Blade replacement for mid span shroud non conforming contour I

### 4. A - APPENDIX A

**NOTE:** The delimiter symbol (-) and checksum character have been added beside the serial numbers. They are not part of the serialization number. Checksum characters have been used by CFM to ensure a correct marking and tracking of the serial number while the successive manufacturing operations.

Table 1

List of fan blades 338-002-114-0 suspected by engines

<u>Engine S/N</u>	<u>Fan Blade S/N</u>	<u>Fan Blade installed position</u>
699533	DE684101-R	1
	DE828351-8	6
	DE827863-1	13
	DD113155-E	16
	DE827174-M	20
	DE828201-U	23
	DE828341-P	24
	DE827896-U	30
	DE827437-H	34
	DE827852-H	35